



**National Water and Wastewater Conference**

# **Extending the Life of Transmission Mains**

**Presented by Stewart Dickson, P. Eng**

# Extending the Life of Transmission Mains

## Outline

- Introduction
- Transmission Main Condition Assessments
  - Challenges
  - Overview – AWWA M77
  - Tools Available
  - Case Study - City of Toronto Riveted Steel Watermain
- Rehabilitation
  - Case Study – Town of New Tecumseth
  - Case Study – City of Toronto



# ABOUT RVA



We're a community of thinkers, innovators, and collaborators who combine human ingenuity with technology and experience to deliver sustained outcomes that make a difference.



**75 Years of Engineering  
Excellence in Canada**



Canadian company  
founded in 1948




Employee owned  
and operated


**#ONERVA**

One company. One team.  
One-stop-shop.

## Challenges

- Transmission mains are the backbone of the water distribution system
- Often lack redundancy and therefore can't be taken out of service
- High demand season is often a No Go for taking pipes offline
- Access – no Maintenance Holes to get in the pipe
- Need to maintain potability – often challenging to disinfect and “recommission” once it's been dewatered
- Limited as-constructed details for older systems






## Table of Contents


1. The Benefits of Condition Assessment for Watermains
2. Building Support for a Condition Assessment Program
3. Planning a Condition Assessment Project or Program
4. Desktop Condition Assessment
5. External Corrosion Surveys
6. Spot Assessment
7. Leak Detection
8. Internal Remote Visual Inspection
9. Physical Entry Inspections
10. Acoustic Velocity Testing
11. Electromagnetic Testing Technologies
12. Magnetic Flux Leakage
13. Condition Assessment of PCCP
14. Hydrostatic Pressure Testing of Existing Pipes
15. Strategies for Economical Assessment of Low-Value Pipes
16. The Next Steps: Using Condition Assessment Information

## Chapter 3: Planning a Condition Assessment Project




Your problem statement is going to determine how far to go

# Transmission Main Condition Assessment Tools



# CASE STUDY – Toronto Riveted Steel Watermains






# CASE STUDY – Toronto Riveted Steel Watermains

## Scope of Assessment

- Desktop study
  - TM-1: RSW Original Wall thickness
  - TM-2 : RSW Failure Mechanisms and Modes
  - TM-3 : RSW Deterioration Rates
  - TM-4 : RSW Failure Thickness
  - TM-5 : RSW Failure Predictions
- Boreholes
- Pipe Excavation and Concrete cores
- Coupon sampling (not completed)
- CCTV Inspection
- Final Report and Recommendations




# CASE STUDY – Toronto Riveted Steel WM



# CASE STUDY – Toronto Riveted Steel WM

---



# CASE STUDY – Toronto Riveted Steel WM



Main #	Length (m)	Diameter (mm; inch)	Year installed (age in 2017) Pipe material	Inspection date	Remaining life / next inspection at age (years)	Structural assessment (risk factor; (FS))	Concrete encasement compressive strength (MPa)	Coefficient of chloride diffusion (cm <sup>2</sup> /year)	Chloride content (initial; exposed face; %)
M29	6,985	1200 mm (48")	1936 (81) Riveted steel	April 2019 & Oct 2019	115 / 112	0.5 – 0.7; (FS: 2 – 1.43)	60.8	7 x 10 <sup>-2</sup>	0.0070; 0.0114
M29B	990	1350 mm (54")	1931 (86) Riveted steel	-	> 200 / 92	0.16 – 0.32; (FS: 6 – 3)	-	7.69 x 10 <sup>-2</sup>	-
M18	460	1050 mm (42")	1948 (69) Riveted steel	Oct. 2019	> 200 / 73	0.44 – 0.6; (FS: 2.3 – 1.67)	36.2	-	0.1225; 0.2551
M28	732	1125 mm (45")	1950 (67) Riveted steel	-	> 200 / 73	0.32 – 0.48; (FS: 3.1 – 2.1)	-	-	-
M7	4,938	900 mm (36")	1951 (66) Welded steel. & Pit cast iron	-	> 200 / 91	0.24 – 0.36; (FS: 4.1 – 2.8)	40.9 – 57.6	3.28 x 10 <sup>-2</sup> – 23.1 x 10 <sup>-2</sup>	0.0115 – 0.0709; 0.0672 – 0.2228

# CASE STUDY – Toronto Riveted Steel WM

## Summary

- City had limited information on the condition of this specific type of pipe in their system
- Desktop review provided theoretical analysis on pipe design and failure mechanisms
- Collection of data for actual pipe locations allowed us to refine the analysis and provide specific data
- CCTV provided the visual pictures to ease the client's mind

A Rolls Royce it is!!



# CASE STUDY – New Tecumseth



## Problem and Investigations

- Existing 400mm diameter (14") HDPE DR 13.5 watermain
- Originally Installed via HDD in 2010
- Sink hole had developed near drain chamber (5 m deep)
- Pipeline deep under the river
- Watermain was drained and inspected
- Found a leaking joint in HDPE pipe (butt fusion welded)



# CASE STUDY – New Tecumseth




## Alternatives and Preferred Solution

- Excavate at location of leak
- Replace pipe across the river (underground or on bridge)
- Installation of internal repair sleeve
- Line a section of the pipe

Install Primus Liner (350mm diameter) across the valley (95 metres) from drain chamber to temp access shaft

Approximate location of leak




# CASE STUDY – New Tecumseth





# CASE STUDY – New Tecumseth



# CASE STUDY – New Tecumseth



## Summary

- Condition Assessment Inspection Tools needed to find the leak
- Since leak was not due to pipe failure, full replacement was not required
- Pipe relatively new, therefore structurally still adequate
- PrimusLine provided an economical, non-structural solution
- Installed from drain chamber to access shaft excavated where more accessible
- Leak detected in April 2020 and pipe back together in service in October 2020




# CASE STUDY – City of Toronto



# CASE STUDY – City of Toronto

## Pipeline History



- Construction completed in 1906
- Dewatered and inspected in 1978 – measurements were smaller than on initial drawings
- ROV inspection completed in 2018 – showed sections failing and in immediate need of rehabilitation



# CASE STUDY – City of Toronto

## Rehabilitation Design


- ROV with 3D sonar survey
  - Established extent of deformation and precise tunnel profile
- Reviewed constructability challenges and options
  - Identified access shaft locations
- Reviewed hydraulics and transients
  - Confirm minimum new inner diameter
- Reviewed several options for new tunnel liner:
  - Hobas/FRP pipe
  - Shotcrete
  - Concrete pressure pipe
  - CIP concrete
  - **Steel pipe with cement mortar lining - Preferred**



# CASE STUDY – City of Toronto



# CASE STUDY – City of Toronto



# CASE STUDY – City of Toronto



## Summary

- Limited Condition Assessments completed on this critical main
- 2018 Inspection indicated it was failing badly and needed immediate rehabilitation
- Full Structural solution was required due to condition of tunnel
- Due to gravity nature of the pipe, hydraulics was very important
- Cement lined pipe sliplined into the horeshoe shaped watermain provided fastest, most economical solution
- Entirely completed during winter/low demand timeline





- Knowing the condition of your Transmission Mains is critical to managing your water system
- Condition Assessment is a formal process that helps you understand the state of your infrastructure
- Consult AWWA M77
- Have a problem statement in mind
- Utilize the tools available to piece the jigsaw puzzle together
- Rehabilitate your mains based on the conditions found and analysis completed

## QUESTIONS?

Stewart Dickson, P.Eng.

Associate Vice President and Principal

R.V. Anderson Associates Ltd.

[sdickson@rvanderson.com](mailto:sdickson@rvanderson.com)