

Opportunistic Watermain Inspection and Sampling Protocol

13 November 2023



Robinson
Consultants

Presenters:

Kevin Bainbridge, C.E.T.

Vice President, Robinson Consultants

Muhit Tanveer, P.Eng.

Senior Project Manager, Robinson Consultants



Robinson
Consultants

Presentation Overview


- City of Hamilton – Background Information
- Opportunistic Inspection & Sampling – Introduction
- Inspection & Sampling Methodology
- Inspection & Sampling Results
- Corrosion Risk Mapping
- Conclusion and Next Steps
- Questions

City of Hamilton – Background Information

- Hamilton is located in Ontario, Canada, at the southwestern end of Lake Ontario
- Total area of 1,138 km² with an approximate population of 536,917 residents (2016 consensus)
- Operates and maintains 2100km of watermains;
 - 176 km of which are classified as a Criticality Level A/B (high/ medium consequence of failure)
- Actively developing and maintaining a critical watermain infrastructure management program for the past 13 years



City of Hamilton – Background Information



City of Hamilton – Background Information

- Likelihood of overall exposure to risk based on:
 - Condition of pipeline (Pipeline Deterioration Factor) (PoF)
 - Consequence of pipeline failure (CoF)
- Business Risk Exposure (BRE) score – PoF x CoF
- 2012 - completed BRE ranking of critical PCCP watermain
- 2013 - completed BRE ranking of critical metallic watermain

City of Hamilton – Background Information

- Trunk Watermains range in size from 400 mm to 2250 mm
- Condition assessments of the highest risk watermains through several ongoing programs:
 - Pre-stressed Concrete Cylinder Pipe (PCCP) Condition Assessment
 - Leak Detection
 - Steel Main Condition Assessment
 - Phase 2 Inspection on Two Pipelines
 - **Opportunistic Watermain Inspection**

City of Hamilton – Background Information

- Since the inception, the City has inspected thirty-one (31) sites on nineteen (19) major trunk watermains
- Eight (8) involved cast iron pipe material, seven (7) were steel pipe, and seventeen (17) were Pre-stressed Concrete Cylinder (PCCP) pipe

Site ID	Site Name	Pipeline	Pipe material
Site 01	Tire Street Site	55	Cast Iron
Site 02	Kenilworth Avenue Site	55	Cast Iron
Site 03	Sherman Avenue Site	18	PCCP
Site 04	Steam Museum Site	18	PCCP
Site 05	West Gate 10 Site	18	PCCP
Site 06	Upper Sherman Avenue Site	33	PCCP
Site 07	Upper Ottawa Street Site	28	PCCP
Site 08	Ainslie Avenue Site	44	PCCP
Site 09	Charlton Avenue East and Catharine Street South	113A	Cast Iron
		139	Cast Iron
Site 10	Greenhill D Site	22	PCCP
Site 11	Justine Avenue & King Street Site	54	Steel
Site 12	Central Avenue & Auburn Avenue	54	Steel
Site 13	Kenilworth Access Site	54	Steel
Site 14	Upper Ottawa Street and Queensbury Drive Site	28	PCCP
Site 15	Rymal Rd. W	106	PCCP

Site ID	Site Name	Pipeline	Pipe material
Site 16	Rymal Rd. W.	106	PCCP
Site 17	Woodward Avenue	62	Cast Iron
Site 18	Garner Rd. E.	35	PCCP
Site 19	Stone Church Rd. E.	31	PCCP
Site 20	Stone Church Rd. E.	123	PCCP
Site 21	275 Robert St Site	111	Cast Iron
Site 22	Robert St & West Ave Site	144	Cast Iron
Site 23	27 Rutherford Ave & 198 Sanford Ave	66	Steel
Site 24	Rutherford at Sanford Ave S	74	Steel
Site 25	168 Sanford Ave S	74	Steel
Site 26	Barton Street East and Kenilworth Ave North	61	Cast Iron
Site 27	Stonechurch Rd. W.	123	PCCP
Site 28	Limeridge Rd E	31	PCCP
Site 29	Upper Ottawa St. & Bowden St.	28	PCCP
Site 30	890 Limeridge Road East	31	PCCP
Site 31	Delena Avenue South/North	54	Steel

Opportunistic Inspection & Sampling - Introduction

- Valuable information during scheduled capital and maintenance not captured
- Establish a watermain inspection and sampling protocol - procedures for collection of soil and watermain samples, testing and analysis.
- Collect pertinent information while the pipe is exposed.
- Emergency repair, periodic maintenance, live connections, valve replacement etc.

Inspection & Sampling Methodology

- A visual inspection with accompanying photographs.
- Cleaning of the exterior surface of the pipe
- Photos taken for any surface defects identified
- Scraping of the pipe surface
- Collection of soil bedding and backfill samples.
- If available, collection of pipe sample for material testing.

Inspection & Sampling Methodology



Opportunistic site inspection – scheduled maintenance, emergency repair, live connections, valve replacement etc.


Inspection & Sampling Methodology



Opportunistic site inspection – scheduled maintenance, emergency repair, live connections, valve replacement etc.

Inspection & Sampling Methodology

- Four (4) soil samples, two (2) of each soil zones - stored in a polyethylene/glass container.
- **Backfill:** two (2) representative backfill samples, 250 mL in size.
- **Bedding:** two (2) representative bedding samples, 250 mL in size.
- Where a pipe sample is removed, a segment of 0.5m to 1m in length.



Inspection & Sampling Methodology

Watermain Pipe Sampling summary

Sample	Location	Quantity	Description	Method	Tests and Analysis*
Watermain (Metallic)	Segment	500mm to 1m	Exposed end, segment or coupon	Rotary cutters or Snap cutters (where possible)	External corrosion characteristics and analysis: Nominal diameter, Wall thickness Pit depth characteristics (max depth, growth rate, and wall penetration) Estimation of the rate of corrosion and age of watermain
					Internal tuberculation characteristics and analysis Inside diameter, Height Cross-Sectional Area
					Internal corrosion characteristics and analysis: Nominal diameter, Wall thickness Pit depth characteristics (max depth, growth rate, and wall penetration)
Watermain (PCCP)	Segment	500mm to 1m	Exposed end, segment or coupon	Rotary cutters	PCCP pipe sample characteristics and analysis: Nominal diameters, Core thickness Can thickness Reinforcing wires thickness Reinforcing wires spacing Mortar thickness Compressive strength of mortar Chloride levels in mortar Porosity of mortar

Inspection & Sampling Results

Soil Samples were evaluated for Corrosion Indicators:
Chloride Concentration

Soil Parameter	Range of Values	Degree of Corrosivity
Chloride Concentration (ppm)	Above 5,000	Severely Corrosive
	1,500 - 5,000	Very Corrosive
	600 - 1,500	Moderately Corrosive
	Below 600	Mildly Corrosive

Soil Parameter	Range of Values	Degree of Corrosivity
Chloride Concentration (ppm)	Above 600	Very Corrosive
	201 - 600	Moderately Corrosive
	50 - 200	Mildly Corrosive
	Below 50	Non Corrosive

A.W. Peabody, Control of Pipeline Corrosion – Second Edition, p. 91, (2001).

Chloride effects on PCCP pipes

Chloride effects on Metallic pipes

Inspection & Sampling Results

Soil Samples were evaluated for Corrosion Indicators:
pH Levels

Soil Parameter	Range of Values	Degree of Corrosivity
pH	Below 5.5	Very Corrosive
	5.5 - 6.5	Moderately Corrosive
	6.5 - 7.5	Neutral
	Above 7.5	Alkaline

A.W. Peabody, Control of Pipeline Corrosion – Second Edition, p. 91, (2001).

pH effects on PCCP and Metallic pipes

Inspection & Sampling Results

Soil Samples were evaluated for Corrosion Indicators:
pH Levels

Soil Parameter	Range of Values	Degree of Corrosivity
Soil Resistivity (ohm-cm)	Below 500	Very Corrosive
	500-1,000	Corrosive
	1,000-2,000	Moderately Corrosive
	2,000-10,000	Mildly Corrosive
	above 10,000	Progressively Less Corrosive

A.W. Peabody, Control of Pipeline Corrosion – Second Edition, p. 88, (2001).

pH effects on PCCP and Metallic pipes

Inspection & Sampling Results

Soil Samples were evaluated for Corrosion Indicators:
Sulphate Concentration

Soil Parameter	Range of Values	Degree of Corrosivity
Sulphate Concentration (ppm)	Above 10,000	Severely Corrosive
	1,500 - 10,000	Very Corrosive
	150 - 1,500	Moderately Corrosive
	Below 150	Mildly Corrosive

G.A. Chandler, WWD, Sulphates and Concrete in the Winnipeg Area, Part 2, 1968, p.11.

Effect of Sulphate on PCCP

Corrosion Risk Mapping

Corrosion Risk Matrix

- The sample with the highest risk level was the governing risk factor for the site.

Corrosion Risk Matrix	
Very Corrosive	1
Corrosive	2
Moderately Corrosive	3
Mildly Corrosive	4
NO DATA	N/A

Corrosion Risk Mapping

Soil Corrosivity Risk level : Site 1 - 13

Site ID	Site Name	Pipeline No.	Corrosion risk Level		
			Backfill	Bedding	Combined
Site 01	Tire Street Site	55	4	2	2
Site 02	Kenilworth Avenue Site	55	4	2	2
Site 03	Sherman Avenue Site	18	4	1	1
Site 04	Steam Museum Site	18	4	1	1
Site 05	West Gate 10 Site	18	4	1	1
Site 06	Upper Sherman Avenue Site	33	3	1	1
Site 07	Upper Ottawa Street Site	28	4	2	2
Site 08	Ainslie Avenue Site	44	4	4	4
Site 09	Charlton Avenue East and Catharine Street South	113A	1	1	1
		139	3	1	1
Site 10*	Greenhill D Site	22	N/A	N/A	N/A
Site 11	Justine Avenue & King Street Site	54	3	4	3
Site 12	Central Avenue & Auburn Avenue	54	4	4	4
Site 13	Kenilworth Access Site	54	4	4	4

*Note: No soil sample for Site 10 and Site 17

Corrosion Risk Mapping

Soil Corrosivity Risk level : Site 14 - 26

Site ID	Site Name	Pipeline No.	Corrosion risk Level		
			Backfill	Bedding	Combined
Site 14	Upper Ottawa Street and Queensbury Drive Site	28	2	4	2
Site 15	Rymal Rd. W	106	2	3	2
Site 16	Rymal Rd. W.	106	3	1	1
Site 17*	Woodward Avenue	62	N/A	N/A	N/A
Site 18	Garner Rd. E.	35	2	1	1
Site 19	Stone Church Rd. E.	31	3	3	3
Site 20	Stone Church Rd. E.	123	3	3	3
Site 21	275 Robert St Site	111	3	3	3
Site 22	Robert St & West Ave Site	144	1	1	1
Site 23	27 Rutherford Ave & 198 Sanford Ave	66	1	1	1
Site 24	Rutherford at Sanford Ave S	74	1	1	1
Site 25	168 Sanford Ave S	74	1	3	1
Site 26	Barton Street East and Kenilworth Ave North	61	1	1	1

*Note: No soil sample for Site 10 and Site 17

Corrosion Risk Mapping

Soil Corrosivity Risk level : Site 27 - 31

Site ID	Site Name	Pipeline No.	Corrosion risk Level		
			Backfill	Bedding	Combined
Site 27	Stonechurch Rd. W.	123	N/A	N/A	N/A
Site 28	Limeridge Rd E	31	2	1	1
Site 29	Upper Ottawa St. & Bowden St.	28	4	3	3
Site 30	890 Limeridge Road East	31	3	3	3
Site 31	Delena Avenue South/North	54	4	4	4

Corrosion Risk Mapping

Corrosion risk level map generated based on using site specific risk table.



Conclusion & Next Step

- Relatively cheaper exercise (during emergency repair, periodic maintenance, live connections, valve replacement etc.)
- Helped identify any trend in the data set
- Prioritization of spending in the management of critical mains
- Continue gaining data and incorporate in corrosion mapping
- Utilize in validation of criticality ranking of PCCP and Metallic watermains

Thank You!

Kevin Bainbridge

Muhit Tanveer

www.rcii.com



Robinson
Consultants